# MCN for Neonatology West of Scotland Neonatal Guideline



# Volume Targeted Ventilation

Indication and use in the Neonatal Unit

# **Contents**

Abbreviations
Set up flowchart
Background
How to Set up
Weaning
Troubleshooting
References
Appendix – previously used set up photos

# **Abbreviations**

BUR - back up rate

ITime – inspiratory time

**PEEP** – peak end-expiratory pressure

**PIP** – peak inspiratory pressure

**PIPmax** – maximum set peak inspiratory pressure

TTV - targeted tidal volume

VG - volume guarantee


**V**<sub>Te</sub> – tidal volume

**VTV** – volume targeted ventilation


# **Set Up Flowcharts**

# Flowchart (Fabian)

1. Baby should be in either SIPPV or SIMV - check current ventilatory requirements including V<sub>Te</sub> (displayed in far right yellow column on home screen)




2. select VG on touch screen (furthermost purple column)



3. calculate required  $V_{Te}$  (usually 5ml/kg, can be 4.5 to 7ml/kg)

4. set max PIP at 30 – 35cmH<sub>2</sub>O and observe, then adjust to 5cm above PIPs pulled (identified in righthand column, first figure)




- 5. check trigger sensitivity (usually 1 on Fabian unless autocycling (see page 13)
- 6. double check VG is selected by pressing green ON button above V<sub>guarantee</sub> tab
- 7. observe response (oxygen saturations, heart rate, work of breathing, blood gas)


# Flowchart for SLE 6000

# ! Please note - all changes require confirmation with selection of tick icon!


1. Baby should be in PTV or SIMV - check current ventilatory requirements including V<sub>Te</sub> (displayed in far right column)




2. Select VTV on user interface (specific button as VTV ON or OFF) – confirm with tick icon




3. calculate required  $V_{Te}$  (usually 5ml/kg, can be 4.5 to 7ml/kg) and use  $\frac{1}{100}$  buttons to input - confirm with tick icon



4. set  $\frac{\text{max PIP}}{\text{max PIP}}$  at 30-35cmH<sub>2</sub>O and observe, then adjust to 5cm above PIPs pulled (identified as large number within max PIP button) - confirm with tick icon



5. check trigger sensitivity (usually 0.2 on SLE unless deliberately increased to avoid autocycling) – this is found under additional parameters tab on left hand side of screen, select value using +/- and confirm with tick icon



6. observe response (oxygen saturations, heart rate, work of breathing, blood gas)


# **Background**

In neonates, volume targeted ventilation is synchronised, volume targeted, pressure limited, time cycled ventilation where a set total volume of air is delivered to the infant using variable amounts of pressure depending on the flow volume measured at the end of the ETT during expiration. This allows for changes in compliance and has been shown amongst preterm infants to have a reduced incidence in ventilator days, air leaks, CLD at 36 weeks corrected gestational age (CGA) combined with death and severe intraventricular haemorrhage (IVH) & periventricular leucomalacia (PVL) when compared with pressure-limited ventilation<sup>1</sup>.

The lungs of very preterm infants are exquisitely sensitive to injury for several reasons. These include surfactant deficiency, structural immaturity and a cartilaginous chest wall. Research in preterm lambs has shown that large distending lung volume and overdistension, rather than high ventilation pressures, can inhibit subsequent responses to surfactant treatment <sup>2,3</sup>.

In Volume Guarantee (VG) or Targeted Tidal Volume (TTV), (the volume targeted ventilation modes on all modern ventilators), the operator sets a target expired volume ( $V_{Te}$ ). The ventilator measures the expired volume for each inflation and adjusts the peak inspiratory pressure (PIP) for subsequent breaths aiming to deliver the approximate required volume. Differences in one PIP to the next are minimised to a range of +/- 3cm  $H_2O$  to avoid overdistension. Each inflation volume is limited to 130% of the previous expiratory volume and compensates for a degree of leak.

Figure 1: pulmonary graphics on VTV




Care should be taken to monitor the set PIP and measured PIP so ensure that tidal volumes are achieved.

Figure 2: maximum PIP not set high enough



Here this is shown by the measured PIPs butting against the set PIP and the tidal volumes are not achieved.



#### **How to Set Up**

# Ventilator Mode

Volume targeted ventilation is most suited to triggered ventilation modes, usually SIPPV though it can be used in SIMV.

The ventilator adjusts PIP for triggered and untriggered breaths separately and it is often noted that the PIP required for the same tidal volume for triggered breaths is much lower than that of untriggered breaths.

The set up of VTV is in addition to the standard set up of triggered ventilation and some good practice is discussed below.

# Setting Target V<sub>T</sub>

Research quotes a range of tidal volumes in the preterm neonate from 3.5 to 8ml/kg<sup>4, 5</sup>. In practice, the optimum starting volume is probably 6ml/kg on the Fabian ventilator, particularly for infants under 1000g.

#### PIP Limit

The maximum set peak inspiratory pressure ( $P_{max}$ ) is not the same as the delivered PIP. The delivered PIP varies from breath to breath to achieve the set  $V_T$ .

The maximum PIP should be set to allow the ventilator to adjust pressures appropriately to achieve the target volume but not to allow excessively high pressures when the ventilator cannot accurately determine the TV. Usually this would be around 5-10 above the current PIP and this does require user input.

Any higher and there may be little warning of changes in lung compliance.

Any lower and the tidal volume may not be achieved, leading to subsequent hypoventilation and atelectasis. In this instance the ventilator will alarm 'low VTe' as it will not be able to achieve the desired VTe with the PIP allowed.

There is no set numerical value required for the  $P_{max}$ . Approximate values are provided in the set up flowcharts but these must be reviewed during this process and individualised to each baby.

Trigger Sensitivity

For preterm infants and to allow for maximum synchrony between baby and ventilator, the flow sensor trigger threshold should be set at its greatest sensitivity (1 on Fabian, 0.2 on SLE5000/6000) Breaths can be inappropriately triggered by rain out (condensation in the circuit). This should be avoided by pointing the flow sensor plug upwards, the use of heated AND humidfied gases and intermittently clearing the ventilator tubing of any condensation.

# Inspiratory Time

An adequate inspiratory time  $(T_i)$  is needed for sufficient delivery of the PIP selected. If it is too short, a high enough PIP will not be achieved for long enough to deliver the set volume. For most preterm infants this will be between 0.32 and 0.36 seconds.

#### Ventilator Rate

The set rate is a back up rate (BUR) whereby the ventilator delivers untriggered inflations, only if the baby's own respiratory rate falls below this, recorded over a set time.

Generally this should sit low enough to encourage spontaneous respiration as these will require less ventilatory support. A back up rate of 40 to 45 breaths per minute is sufficient but may need increased in infants with poor respiratory drive.

#### Flow Rate

This is automatically set on SLE and Fabian ventilators but in the use of Drager models, should be 8 litres/minute.

#### **PEEP**

To maintain functional residual capacity, an adequate peak end expiratory pressure (PEEP) is essential. It improves oxygenation and prevents at electasis. The optimum PEEP for intubated preterm infants is at generally 5 to 6cm  $H_2O$ . But higher settings may be required in certain infants e.g CLD, pulmonary haemorrhage.

#### Weaning

When optimally applied to preterm infants, this ventilator mode lends itself to automatic weaning. As the baby's lung compliance improves, the PIP reduces on a breath to breath basis rather than on steps guided by blood gases or oxygen requirement. Equally, if lung compliance is worsening, the ventilator will respond with higher PIPs to maintain the set VT.

In infants who are spontaneously breathing, and well synchronised on a patient triggered mode, the main adjustable variables will be the VT and oxygen concentration. Such infants will be setting their own rate.

Using the usual parameters of need for supplemental oxygen and CO2 clearance on blood gases the set VT can be adjusted to deliver more or less ventilation. This is usually done in 0.5ml/kg increments.

In practice, in those infants with good lung compliance, delivered VT between 4 to 6 ml/kg can often be delivered with low PIPs and little variation in delivered PIP. Therefore the PIPs 'pulled' can be a better indicator of the ability of an infant to be weaned or extubated once their requirement is less than 5ml/kg or lower. In such cases, if the patient is triggering well with stable oxygenation and good gases, it is time to extubate.

Below these levels, the ventilator can be effectively providing CPAP via an endotracheal tube with a small diameter, and a corresponding marked increase in airway resistance, which can worsen at electasis and respiratory distress.

In some infants, extubation cannot be considered for other clinical reasons e.g. poor respiratory drive, airway abnormalities. Here, pressure-limited ventilation (at a low PIP) may be more appropriate to prevent derecruitment.

However, this ventilation mode responds intuitively to lung compliance and so will allow for easier, earlier extubation in the majority of babies.

# **Troubleshooting**

#### Common Alarms

# VT Not Reached

This can occur if:

- o the  $P_{max}$  hasn't been set high enough (see figure 2). In a well synchronised infant then you may need to increase the maximum PIP to allow the set  $V_{Te}$  to be achieved (>30 35cm  $H_2O$ ). If PIPs above 30 35cm  $H_2O$  are consistently being pulled, the infant may be requiring considerable ventilatory support and should be discussed with a consultant.
- there is a problem with the baby or equipment.
   Usual checks of the ETT and baby should apply, with exclusion of tube blockage or displacement and air leak


Figure 3: ETT displaced as seen on pulmonary graphics



- o the baby is splinting.
  - This is active expiration against ventilator inspiration; it can also be thought of as diaphragmatic braking (see figure 5). It will appear as recurring drops in  $V_{Te}$ s despite increasing PIPs
- o the flow rate is too low.
  - This is solely a concern in the use of Drager ventilators as flow rate is automatically set on SLE and Fabian ventilators.
- o the iTime is too short.
  - It can be assessed via the ventilator graphics.
  - On a pressure-time graph, an adequate  $T_i$  is demonstrated as a short plateau after the PIP is delivered then a return to baseline before expiration.
  - On a flow-time graph, if Ti is too short, the flow wave will end abruptly at the end of inflation before reaching the baseline and the tidal volume will have a sharp peak.
  - If too long, the pressure plateau will be held after inflation flow has ceased with no subsequent increase in  $V_T$ .

Figure 4: effect of inspiratory time

# Too short



Too long




Figure 5: splinting as seen on pulmonary graphics



#### Leaks

Leaks around a neonatal endotracheal tube are common as they are usually uncuffed. This can affect the delivery of any type of ventilation. In VTV this is partially compensated by measuring the expired gas rather than the inspired gas as it is a more accurate measure of the actual tidal volume. However with all ventilation modes, leak is overcome by delivery of higher flow and pressure to compensate for inspiratory flow that does not reach the lungs.

With VTV, the Fabian ventilator will tolerate up to 50% leak with appropriate PIPs delivered to this point. However beyond this range, there may be initial concerns that rising PIPs are due to worsening lung disease. Thereafter, with ongoing leak and falling measurements of expired  $V_T$ , the PIP delivered may be insufficient to achieve the actual required volume with subsequent atelectasis and worsening ventilation.

It may be appropriate to replace with a larger diameter endotracheal tube.

Figure 6: leaks as seen on pulmonary graphics



In keeping with all modes of triggered ventilation, sometimes a baby does not do well on VTV. This may be caused by:

- An inappropriate iTime
   Consider reducing this if long (>0.4 0.45 seconds). This should reduce interrupted expiration.
- A BUR too close to the baby's spontaneous respiration rate
   Reduce the rate to a minimum of 10 breaths per minute below the spontaneous rate.
- A baby in pain or distress
   Consider analgesia or sedation
- Autocycling

This is the inappropriate triggering of breaths due to causes other than the infant's inspiratory effort. Causes include cardiac impulses, oscillation of secretions or humidity in the ventilator circuit or an inappropriate trigger sensitivity. This can be excluded by observing the baby's spontaneous respiratory rate with a trial of a lower BUR. Solutions include adjusting the ventilator tubing, reducing rain out and adjusting trigger sensitivity as previously outlined.

Figure 7: asynchrony and interrupted expiration as seen on pulmonary graphics




Figure 8: autocycling as seen on pulmonary graphics



Those ELBW babies most likely to benefit from VTV modes are those most likely to suffer common problems with endotracheal leak and splinting, therefore troubleshooting for these is of high importance.

# Derecruitment

In some babies, despite the ventilator delivering the set VT with good synchrony with the patient, a rising oxygen requirement can be the first sign of lung derecruitment. A chest X-ray can be performed to check for small volume lung fields. A trial of pressure limited ventilation will help recruit partially collapsed lungs but an early return to volume targeted ventilation is then indicated to prevent barotrauma and hypocapnia as previously described.



# References


- 1. Wheeler K, Klingenberg C, McCallion N, Morley CJ, Davis PG. Volume-targeted versus pressure-limited ventilation in the neonate. *Cochrane Database Syst Rev* 2010; 11: CD003666.
- 2. Bjorklund, LJ, Ingimarsson J, Curstedt T, John J, Robertson B, Werner O, et al. Manual ventilation with a few large breaths at birth compromises the therapeutic effects of subsequent surfactant replacement in immature lambs. Pediatr Res 1997;42:348-55
- 3. Hernandez LA, Peevy KJ, Moise AA, Parker JC. Chest wall restriction limits high airway pressure-induced lung injury in young rabbits. *J Appl Physiol* 1989; 66: 2364–2368.
- 4. Vilstrup CT, Bjorklund LJ, Werner O, Larsson A. Lung volumes and pressure-volume relations of the respiratory system in small ventilated neonates with severe respiratory distress syndrome. *Pediatr Res* 1996; 39: 127–133.
- 5. te Pas AB, Davis PG, Kamlin CO, Dawson J, O'Donnell CP, Morley CJ. Spontaneous breathing patterns of very preterm infants treated with continuous positive airway pressure at birth. *Pediatr Res* 2008; 64: 281–285.

# Appendix SLE 5000 Set Up


1. Baby should be in PTV or SIMV - check current ventilatory requirements including V<sub>Te</sub> (displayed in far right orange column on home screen)




2. Select TTV<sup>plus</sup> on user interface (specific button as TTV<sup>plus</sup> ON or OFF)



- 3. calculate required  $V_{Te}$  (usually 5ml/kg, can be 4.5 to 7ml/kg)
- 4. set max PIP at 30-35cmH<sub>2</sub>O and observe, then adjust to 5cm above PIPs pulled (identified as large number within max PIP button)



5. check trigger sensitivity (usually 0.2 on SLE unless autocycling) by selecting Set Trigger dotted line on flow graph will begin to flash – use arrows to adjust level as appropriate



# **Document Title**

WoS\_VolumeTargettedVentilation\_Neonates

# **Document Authors**

Dr Cliodhna Godden, Neonatal Grid Trainee, RHC Dr Chris Lilley, Consultant Neonatologist, PRM

# Update 2022

Dr Julie Aitken, Neonatal Grid Trainee, RHC Dr Niall Donaldson, ST2 Paediatrics, RHC Dr Manahara Ratnayake, FY2 Neonates, RHC

# **Implementation / Review Dates**

Implementation Date 01/05/20 Review Date 01/05/2026